

Site Boundary Indicated by Red Line

Adjacent unit not surveyed, not part of this application

Adjacent unit not surveyed, not part of this application

Second FFL 5775

Original sash windows to front elevation are to be repaired/refurbished where necessary, refer to conservation report

First FFL 2800

Ground FFL 0




NOT PART OF THIS APPLICATION No.8 Skeffington Street

No.6 Skeffington Street Protected Structure


NOT PART OF THIS APPLICATION No.4 Skeffington Street Protected Structure

### Existing - Elevation 1 - Front

1 : 50

-  Existing Wall
-  Element to be Demolished
-  Proposed Wall

Note  
Do not scale.  
Use figured dimensions only.  
This drawing is to be read in conjunction with all relevant specifications and drawings.  
All dimensions to be checked on site.



Site Boundary Indicated by Red Line

Non-original windows to rear elevation are to be replaced with sash style windows to match original windows to front elevation, refer to conservation report

Adjacent unit not surveyed, not part of this application

Adjacent unit not surveyed, not part of this application

Flat roofed single storey extension to rear to be demolished.

2215

### Existing - Elevation 2 - Rear

1 : 50

Stage:	<b>PLANNING</b>		
Client:	Frank Finnegan		
Project:	No. 6 Skeffington Street, Wexford		
Drawing:	Existing - Elevations		
Date:	Aug 2025	Scale:	1 : 50 @A3
Drawing No:	PL-300		

RECEIVED: 19/08/2025